



Product Change Notice

PCN Number: 16-0209-01A
Issue Date: 23-JUNE-2016

Exar Corporation

www.exar.com | Support: customersupport@exar.com

PRODUCTS AFFECTED:

iML1122CC	iML1142HS	iML2122CB	iML2122CC
iML2122CL	iML2122CL-TR	iML2142DA	iML2142HS
iML2142HS-TR	iML7512	iML7512CC	iML7512DB
iML7514DA	iML7514HS	iML7514HS	iML7514HS
iML7814HS	iML7814HS-HF	iML7822DB	iML7822DBT-HF
iML7822DBTLG	iML7824DA	iML7824DA-TR	iML7824HS(1008)
iML7824HS(1022)	iML7824HS	iML7972ACL-TR	iML7972CL
iML7972CL-TR	iML7976	iML7976LB-TR	iML8811
iML9824HS-TR			

CHANGE CATEGORY:

<input type="checkbox"/> Material	<input type="checkbox"/> Process	<input type="checkbox"/> Package
<input type="checkbox"/> Design	<input type="checkbox"/> Datasheet	<input type="checkbox"/> Packing/Shipping
<input checked="" type="checkbox"/> Other: Alternate site		

DESCRIPTION OF CHANGE:

Qualification of ANST as an alternate manufacturing site.

Addendum:

Additionally, qualification of copper wire bonding assembly.

IMPACT OF CHANGE:

There is no change to product form, fit or function.

TARGET IMPLEMENTATION DATE: 23-SEPTEMBER-2016

Please contact customer support (customersupport@exar.com) for sample date availability or qualification data

PROPRIETARY INFORMATION

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.