



Subject: Product Discontinuation Notification

To whom it may concern,

This is notification that the part numbers listed below will be discontinued by Exar Corporation, effective immediately:

Ordering Part Number	Suggested Part Replacement	Functional equivalent	Pin Compatible
CLC1001ASO8	CLC1001ISO8	X	X
CLC1001ASO8MTR	CLC1001ISO8MTR	X	X
CLC1001ASO8X	CLC1001ISO8X	X	X
CLC1001AST6	CLC1001IST6	X	X
CLC1001AST6MTR	CLC1001IST6MTR	X	X
CLC1001AST6X	CLC1001IST6X	X	X
CLC1002ASO8	CLC1002ISO8	X	X
CLC1002ASO8MTR	CLC1002ISO8MTR	X	X
CLC1002ASO8X	CLC1002ISO8X	X	X
CLC1002AST6	CLC1002IST6	X	X
CLC1002AST6MTR	CLC1002IST6MTR	X	X
CLC1002AST6X	CLC1002IST6X	X	X
CLC1003ASO8	CLC1003ISO8	X	X
CLC1003ASO8MTR	CLC1003ISO8MTR	X	X
CLC1003ASO8X	CLC1003ISO8X	X	X
CLC1003AST5	CLC1003IST5	X	X
CLC1003AST5MTR	CLC1003IST5MTR	X	X
CLC1003AST5X	CLC1003IST5X	X	X
CLC1007ASO8	CLC1007ISO8	X	X



Ordering Part Number	Suggested Part Replacement	Functional Equivalent	Pin Compatible
CLC1007ASO8MTR	CLC1007ISO8MTR	X	X
CLC1007ASO8X	CLC1007ISO8X	X	X
CLC1007AST5	CLC1007IST5	X	X
CLC1007AST5MTR	CLC1007IST5MTR	X	X
CLC1007AST5X	CLC1007IST5X	X	X
CLC2007AMP8	CLC2007IMP8	X	X
CLC2007AMP8MTR	CLC2007IMP8MTR	X	X
CLC2007AMP8X	CLC2007IMP8X	X	X
CLC2007ASO8	CLC2007ISO8	X	X
CLC2007ASO8MTR	CLC2007ISO8MTR	X	X
CLC2007ASO8X	CLC2007ISO8X	X	X
CLC2023AMP8	CLC2023IMP8	X	X
CLC2023AMP8MTR	CLC2023IMP8MTR	X	X
CLC2023AMP8X	CLC2023IMP8X	X	X
CLC2023ASO8	CLC2023ISO8	X	X
CLC2023ASO8MTR	CLC2023ISO8MTR	X	X
CLC2023ASO8X	CLC2023ISO8X	X	X
CLC4007ASO14	CLC4007ISO14	X	X
CLC4007ASO14MTR	CLC4007ISO14MTR	X	X
CLC4007ASO14X	CLC4007ISO14X	X	X
CLC4007ATP14	CLC4007ITP14	X	X
CLC4007ATP14MTR	CLC4007ITP14MTR	X	X
CLC4007ATP14X	CLC4007ITP14X	X	X

No further purchase orders will be accepted for these devices. For future requirements of the discontinued items, please refer to the suggested replacements.

If you should have any questions regarding this notice, please contact Lisa Bedard via email at Lisa.Bedard@Exar.com or customersupport@exar.com.